



**COMMERCIAL COOLING  
PAR ENGINEERING, INC.**

**BUYER BEWARE  
ALL WALK-INS ARE NOT THE SAME**

RATING	INDUSTRY NOMENCLATURE	SKETCH	EXPLANATION OF MAJOR DIFFERENCES
<p><u>BAD</u></p> <p><b>COMPETITOR</b></p>	<p>Standard 2 x 4 wood frame</p>		<p>All the same problems as above with much more chances of air escaping. Without tongue and groove (Very poor construction)</p> <p>Exposed screws that are unsightly and causes tear. The sheet metal transfers cold and moisture to the center and will cause ice up, expansion and destroy the joints.</p>